

## Novedades al 13/05/2016

Código	Marca	Descripción	Cc	Novedad
1-65 D	KKK	MB	Buje KP35	INHABILITACION
2-01 14-10[10]	OFF FACTORY		Anillo cierre L.C. .500-1.60 TO4-S2B-S2A-HT12-CT20-GT32-GT35	INHABILITACION
2-01 2-1	MERCOSUR		Anillo cierre L.C. .500-1.60 TO4-S2B-S2A-HT12-CT20-GT32-GT35	INHABILITACION
2-01 2-10[10]	MERCOSUR		Anillo cierre L.C. .500-1.60 TO4-S2B-S2A-HT12-CT20-GT32-GT35	INHABILITACION
2-01 2-100[100]	MERCOSUR		Anillo cierre L.C. .500-1.60 TO4-S2B-S2A-HT12-CT20-GT32-GT35	INHABILITACION
2-01 2-50[50]	MERCOSUR		Anillo cierre L.C. .500-1.60 TO4-S2B-S2A-HT12-CT20-GT32-GT35	INHABILITACION
2-01 A 2-10[10]	MERCOSUR		Anillo cierre L.C. .510-1.60 TO4-S2B-S2A-HT12-CT20-GT32-GT35	INHABILITACION
2-01 A 2-50[50]	MERCOSUR		Anillo cierre L.C. .510-1.60 TO4-S2B-S2A-HT12-CT20-GT32-GT35	INHABILITACION
2-03 2-10[10]	MERCOSUR		Anillo cierre L.C. .625-1.60 S3B-3LM-2LS-ETC.	INHABILITACION
2-04 2-1	MERCOSUR		Anillo cierre L.C. .6875-1.70 TV-T12-TA45/51-GT42/45-UTV	INHABILITACION
2-04 2-10[10]	MERCOSUR		Anillo cierre L.C. .6875-1.70 TV-T12-TA45/51-GT42/45-UTV	INHABILITACION
2-04 2-50[50]	MERCOSUR		Anillo cierre L.C. .6875-1.70 TV-T12-TA45/51-GT42/45-UTV	INHABILITACION
2-04 A 2-10[10]	MERCOSUR		Anillo cierre L.C. .6975-1.70 TV-T12-TA45/51-GT42/45	INHABILITACION
2-05 2-10[10]	MERCOSUR		Anillo cierre L.C. .635-1.60 H1B-H2A-H2D-H1E-HX35/40	INHABILITACION
2-06 2-1	MERCOSUR		Anillo cierre L.C. .552-1.40 K14-K16-RHB6 (K24-alg. mod.)	INHABILITACION
2-06 2-10[10]	MERCOSUR		Anillo cierre L.C. .552-1.40 K14-K16-RHB6 (K24-alg. mod.)	INHABILITACION
2-06 2-50[50]	MERCOSUR		Anillo cierre L.C. .552-1.40 K14-K16-RHB6 (K24-alg. mod.)	INHABILITACION
2-09 14-1	OFF FACTORY		Anillo cierre L.C..394-1.00 RHB3-RHB4-RHB5-TD04-TF035-RHF4-RHF	INHABILITACION
2-10 2-10[10]	MERCOSUR		Anillo cierre L.C. .4882-1.20 RHB5-RHB6-TD05-TD06-GT12 (12.40 mm.	INHABILITACION
2-14 2-1	MERCOSUR		Anillo cierre L.C. 10 mm.-1.40 K03-KP35-T15 ( Ø 10 mm)	INHABILITACION
2-14 2-10[10]	MERCOSUR		Anillo cierre L.C. 10 mm.-1.40 K03-KP35-T15 ( Ø 10 mm)	INHABILITACION
2-14 2-50[50]	MERCOSUR		Anillo cierre L.C. 10 mm.-1.40 K03-KP35-T15 ( Ø 10 mm)	INHABILITACION
2-15 2-1	MERCOSUR		Anillo cierre L.C. 11 mm.-1.20 CT12-CT12B-P/Tbo 17201-0L030/0L040	INHABILITACION
2-19 2-1	FRANCO KITS		Anillo cierre L.C. 8 mm- 0.80mm RHB31 - TD02 - TD03	INHABILITACION
2-20 2-10[10]	MERCOSUR		Anillo cierre L.C.14.3 mm.-1.59 GT3776 - MP40	INHABILITACION
2-21 2-10[10]	MERCOSUR		Anillo cierre L.C. 22 mm.-2.00 S400	INHABILITACION
2-22 2-10[10]	MERCOSUR		Anillo cierre L.C. 7/16" - 1.15 S1B	INHABILITACION
2-25 2-10[10]	MERCOSUR		Anillo cierre L.C. 18 mm.-1.60 S300	INHABILITACION
2-26 1-10[10]	MERCOSUR		Anillo cierre L.C. 16mm.-1.51 S200	INHABILITACION
2-26 2-1	MERCOSUR		Anillo cierre L.C. 16mm.-1.51 S200	INHABILITACION
2-26 2-10[10]	MERCOSUR		Anillo cierre L.C. 16mm.-1.51 S200	INHABILITACION
3-01 2-100[100]	MERCOSUR		Anillo cierre L.T. .710-1.60 TO4-S2A-HT12-CT20-GT32-GT35	INHABILITACION
3-01 A 2-10[10]	MERCOSUR		Anillo cierre L.T. .710-1.80 TO4-S2A-HT12-CT20-GT32-GT35	INHABILITACION
3-01 D 2-10[10]	MERCOSUR		Anillo cierre L.T. .720-1.60 TO4-S2A-HT12-CT20-GT32-GT35	INHABILITACION
3-03 2-10[10]	MERCOSUR		Anillo cierre L.T. .760-1.60 3LM-S2B-H1B-H2D-HX35/40	INHABILITACION
3-03 A 2-1	MERCOSUR		Anillo cierre L.T. .760-1.80 3LM-S2B-H1B-H2D-HX35/40	INHABILITACION
3-03 A 2-10[10]	MERCOSUR		Anillo cierre L.T. .760-1.80 3LM-S2B-H1B-H2D-HX35/40	INHABILITACION
3-03 B 2-10[10]	MERCOSUR		Anillo cierre L.T. .760-2.00 3LM-S2B-H1B-H2D-HX35/40	INHABILITACION
3-03 C 2-10[10]	MERCOSUR		Anillo cierre L.T. .760-2.20 3LM-S2B-H1B-H2D-HX35/40	INHABILITACION
3-04 A 2-1	MERCOSUR		Anillo cierre L.T. .823-1.80 TV-T12-TA45/51 - GT37/40/42/45	INHABILITACION
3-04 A 2-10[10]	MERCOSUR		Anillo cierre L.T. .823-1.80 TV-T12-TA45/51 - GT37/40/42/45	INHABILITACION
3-06 2-1	MERCOSUR		Anillo cierre L.T. .875-1.60 E-4LE-4LF-3LD	INHABILITACION
3-07 14-1	OFF FACTORY		Anillo cierre L.T. .552-1.40 K03-K14-K16	INHABILITACION
3-07 14-10[10]	OFF FACTORY		Anillo cierre L.T. .552-1.40 K03-K14-K16	INHABILITACION
3-08 A 2-1	MERCOSUR		Anillo cierre L.T. 1.000-1.80 S3A-S3B-S4A-S4D	INHABILITACION
3-09 A 2-10[10]	MERCOSUR		Anillo cierre L.T. .625-1.80 TB02-TD04-TF035-S1B-T15	INHABILITACION
3-09 A 2-50[50]	MERCOSUR		Anillo cierre L.T. .625-1.80 TB02-TD04-TF035-S1B-T15	INHABILITACION
3-09 B 2-10[10]	MERCOSUR		Anillo cierre L.T. .625-2.00 TB02-TD04-TF035-S1B-T15	INHABILITACION
3-09 D 2-1	MERCOSUR		Anillo cierre L.T. .635-1.60 TB02-TD04-TF035-S1B-T15	INHABILITACION
3-09 D 2-10[10]	MERCOSUR		Anillo cierre L.T. .635-1.60 TB02-TD04-TF035-S1B-T15	INHABILITACION

3-10 A 2-1	MERCOSUR		Anillo cierre L.T. 1.020-1.80 T18-BTV-UTV-TV75/85	INHABILITACION
3-13 2-1	MERCOSUR		Anillo cierre L.T. .689-1.60 TD05	INHABILITACION
3-21 2-1	MERCOSUR		Anillo cierre L.T. .750-1.60 HX50-HX35 Iveco Tector	INHABILITACION
3-21 A 2-1	MERCOSUR		Anillo cierre L.T. .750-1.80 HX50	INHABILITACION
3-21 A 2-10[10]	MERCOSUR		Anillo cierre L.T. .750-1.80 HX50	INHABILITACION
3-21 B 2-1	MERCOSUR		Anillo cierre L.T. .750-2.00 HX50	INHABILITACION
3-24 A 2-10[10]	MERCOSUR		Anillo cierre L.T. 26 mm.-2.20 S400	INHABILITACION
3-25 2-1	MERCOSUR		Anillo cierre L.T. 22 mm.-2.00 S300	INHABILITACION
14-34 A	MERCOSUR		Placa trasera S400 (Aluminio) (168094) (MCS)	INHABILITACION
16-206 K	OFF FACTORY		Rueda turbina GT37 Fund. K418 (434461-0004) (Off Factory) Use 44-02	INHABILITACION
20-16 B	GARRETT		Proteccion Térmica TV81/84/85 Fund.(407657-0004) (Turbolar)Use 20-7	INHABILITACION
34-17 B	OFF FACTORY		Válvula CT16 p/tbo 0L030 (Off Factory) Use 34-08EB	INHABILITACION
38-118 K	TURBOLAR		Rueda compresora K24 (5324 123 2010) p/ Tbo. K14 (6446) (Turbolar)	INHABILITACION
38-306 B	OFF FACTORY		Rueda comp.MFS CCW K24 (5324 123 2039)-p/turbos K16 vs.(KTS)(OF	INHABILITACION
38-393 B	OFF FACTORY		Rda. Comp. GT35 (posible 434292-0007) (Øm:56,9; ØM:76,2; Typ:7,0)(	INHABILITACION
108-21	I.H.I.		Turbo Nuevo IHI VT10 VF420088 RHF4 Mitsubishi L200 2,5 TD	INHABILITACION
115-25	MASTER POWER		Conj. cent. 803010 TA5102 Volvo NL12	INHABILITACION
139-17	ROTOMASTER		C.C.R. Nuevo Rotomaster 167387 S3BSL120 Caterpillar Vs.	INHABILITACION
187-03	ALTERNATIVOS SJP		Turbo Nuevo 17201-67010 CT12B Toyota Hilux 3.0 TD4 (SJP)	INHABILITACION
204-20	ALTERNATIVOS SIT		Turbo Nuevo 751851-0001 GT1646V Golf-A3 TDI-Touran TDI (SIT)	INHABILITACION
205-65	ALTERNATIVO STO		Turbo 166643 S400 M.B.O400RSL/LS/LK/LB2325 Motor OM447LA-Euro	INHABILITACION
402-11	MARCAS VARIAS		Vaso Aloj. turbina Garrett GT15-9	INHABILITACION
1-05 C	MERCOSUR	MB	Buje 2LD-2LS (ss 3LD)	ALTA
1-40 A	MELETT	MB	Buje BTG-UTV75-BTV75/85-TV85	ALTA
1-51 A	MELETT	MB	Buje S200	ALTA
2-05 D 1-1	MERCOSUR		Anillo cierre L.C. .635-1.60 H1B-H2A-H2D-H1E-HX35/40	ALTA
2-09 D 1-1	MERCOSUR		Anillo cierre L.C..394-1.00 RHB3-RHB4-RHB5-TD04-TF035-RHF4-RHF	ALTA
2-14 D 1-1	MERCOSUR		Anillo cierre L.C. 10 mm.-1.40 K03-KP35-T15 ( Ø 10 mm)	ALTA
2-15 D 1-1	MERCOSUR		Anillo cierre L.C. 11 mm.-1.20 CT12-CT12B-P/Tbo 17201-0L030/0L040	ALTA
2-21 D 1-1	MERCOSUR		Anillo cierre L.C. 22 mm.-2.00 S400	ALTA
2-25 D 1-1	MERCOSUR		Anillo cierre L.C. 18 mm.-1.60 S300	ALTA
2-26 D 1-1	MERCOSUR		Anillo cierre L.C. 16mm.-1.51 S200	ALTA
3-07 D 1-1	MERCOSUR		Anillo cierre L.T. .552-1.40 K03-K14-K16	ALTA
3-07 E 1-1	MERCOSUR		Anillo cierre L.T. .552-1.40 K03-K14-K16	ALTA
3-07 G 1-1	MERCOSUR		Anillo cierre L.T. .552-1.40 K03-K14-K16	ALTA
3-16 A 1-1	MERCOSUR		Anillo cierre L.T. HT12-CT12/12B-P/Tbo 17201-0L030/0L040	ALTA
3-16 B 1-1	MERCOSUR		Anillo cierre L.T. HT12-CT12/12B-P/Tbo 17201-0L030/0L040	ALTA
3-16 D 1-1	MERCOSUR		Anillo cierre L.T. HT12-CT12/12B-P/Tbo 17201-0L030/0L040	ALTA
3-16 E 1-1	MERCOSUR		Anillo cierre L.T. HT12-CT12/12B-P/Tbo 17201-0L030/0L040	ALTA
11-06 C[10]	OFF FACTORY		Tuerca tur.K27-S2B-S200-Holset(7-1.00 izq.)Llave hex.13 (3590306)(OF	ALTA
11-17[10]	MARCAS VARIAS		Tuerca eje turbina S2B (7-1.00 der.)	ALTA
14-205 A	MELETT		Placa trasera CIES – RHF55 (ØM 161,50mm – Øal. RC 60,90mm) (EUS	ALTA
14-90 A	MELETT		Placa trasera KP39 – Espalda bombe (5443 152 3005) (EUS)	ALTA
15-05 L	TURBOLAR		Rueda compresora 4LE 32/4.00 (510832) (Turbolar)	ALTA
16-283 K#	OFF FACTORY		Rda.Turb. TV7506 (447386-04) K418 (p/anillo 3-10)(alabe doblado)(OFA	ALTA
16-340 K#	OFF FACTORY		Rda.Turb. TV7504 (447386-01) K418 (p/anillo 3-10)(alabe doblado)(OFA	ALTA
16-373 A	MELETT		Rueda turbina BV40 (5440 120 5000) (EUS)	ALTA
16-374 A	MELETT		Rueda turbina HX35 (3595832) p/dos anillos de 1,71 de espesor (EUS)	ALTA
16-63 K	OFF FACTORY		Rueda turbina TB2509 (435257-0003) (ØM 53,1 – Øm 39,4) (Off Factory	ALTA
16-74 K#	OFF FACTORY		Rda.Turb. TV78 (442479-02) Fund. K418 Caterpillar (alabe doblado)(OF	ALTA
23-316 A	MELETT		Cuerpo central BV40 (5440 150 4003) (EUS)	ALTA
24-59 B	OFF FACTORY		Carcasa compresora CT16 – p/Tbo 0L030 (Off Factory)	ALTA
34-08EB	OFF FACTORY		Válvula CT16 p/tbo 0L030 (Off Factory) Use 34-17 B	ALTA
34-09EB	OFF FACTORY		Válvula K03 (5825 110 5042 / 5825 110 5097) p/tbo 5303 970 0121 (OF	ALTA
35-43 B[5]	OFF FACTORY		Kit desgaste axial H2A-H1C–H1E Collar(04-09)–Arand. c/sep.(08-10)(OF	ALTA

38-338 L	TURBOLAR	Rueda compresora S200 (172244) (Turbolar)	ALTA
38-351 A	OFF FACTORY	Rda.MFS CCW K04 RS2 Sprinter (5306 123 2016)(Øm 39,3 – ØM 59,2)	ALTA
38-468 B	OFF FACTORY	Rueda compresora TV6114 (409318-0003) (ØM 97,8 – Øm 69,1) (OFA)	ALTA
38-469 B	OFF FACTORY	Rueda comp.T04R (p/tbo 465981-0007) (ØM84,0–Øm 66,6–typ 7,5) (OF	ALTA
38-52 L	TURBOLAR	Rueda compresora 4LGZ IVECO 190.33 (Turbolar)	ALTA
108-21 X	I.H.I.	Turbo Nuevo IHI VT10 VF420088 RHF4 Mitsubishi L200 2,5 TD OP3 (CI	ALTA
111-74	GARRETT	Conjunto central 433289-0424 GT2556S Perkins Industrial Vs.	ALTA
127-02	HITACHI	Turbo HT10-X147 (047-115) Grand Vitara	ALTA
131-14E	TURBOLAR	Conjunto central 443853-0019 TB0216 Jeep Cherokee	ALTA
131-31F	TURBOLAR	Conjunto central 433289-0424 GT2556S Perkins Industrial Vs.	ALTA
132-17C	TURBOLAR	Conjunto Nuevo K04-2275 (0507) Audi A3 – TT	ALTA
205-70	ALTERNATIVO STO	Turbo VT10 VF420088 RHF4 MHI L200 2.5 TD (STO)	ALTA
205-82	ALTERNATIVO STO	Turbo Nuevo VICC VE430023 8971480760 RHF5 Isuzu 3.1 Ecologico (	ALTA
205-83	ALTERNATIVO STO	Turbo Nuevo K16-2471 (7129) Mercedes Benz OM904LA-E3 (STO)	ALTA
205-84	ALTERNATIVO STO	Turbo 316699 S400 Mercedes Benz Actros OM501-E2 (STO)	ALTA
205-85	ALTERNATIVO STO	Turbo Nuevo 751851-0001 GT1646V Golf-A3 TDI-Touran TDI (STO)	ALTA
205-86 F	ALTERNATIVO STO	Turbo K03-1870 (0003) VW-Audi (Aloj.Rda.Turbina Ø38,4mm) (STO)	ALTA
205-87 F	GARRETT	Tbo.787556-0017 GTB1749VK F.Transit 2,2 Duratorq Euro V(s/actua.)(	ALTA
205-88	ALTERNATIVO STO	Turbo Nuevo Alt. 318844 S200G Deutz – Motor BF6M1013FC (=318729)	ALTA
303-04	MARCAS VARIAS	Remaches est. 0 - 3/16 x 100	ALTA
303-04[3]	MARCAS VARIAS	Remaches est. 0 - 3/16 x 100	ALTA
10-23 D	TURBOLAR	Cojinete axial TV84-TV85-GT42-GT45 Material ferroso (443685-0001)(T	PRECIO
14-02	SCHWITZER	Placa trasera 3LM (197652)	PRECIO
101-141	GARRETT	806291-0002 Tbo.Nvo.Garrett GTC1244VZ Peugeot 308 GTI – Citroen	PRECIO
102-64	KKK	Turbo Nuevo KKK BV50-2277 (0054) A4 3,0TDi – Touareg 3,0	PRECIO
108-21 Y	I.H.I.	Turbo Nuevo IHI VT10 VF420088 RHF4 Mitsubishi L200 2,5 TD OP2	PRECIO
109-25	MITSUBISHI	Tbo.Nvo.MHI 49173-07508 TD025S2 Citr.vs.-Peu.vs DV6B DV6ATED4	PRECIO
127-02 A	HITACHI	Turbo Hitachi HT10-X147 Grand Vitara (047-115) (Reman)	PRECIO
171-57	MELETT	Conj. central BV40-1874 VW Passat–Touran 2,0Lts. TDI – Rda.Comp.	PRECIO
15-13 K	TURBOLAR	Rueda compresora TA0302 (409096-0011) (Turbolar)	OFERTA
15-48 K	TURBOLAR	Rueda compresora TB0264 Peug. 405 (Ø35.6) (410450-0013) (Turbolar)	OFERTA
15-58 K	TURBOLAR	Rueda compresora APL821 (Ø 38,6) (447449-0006) (TUR)Use 38-01 o 3	OFERTA
15-84 K	TURBOLAR	Rueda compresora RHB51P - VA55B - VA59B (NN136614) (Turbolar)	OFERTA
15-86 K	TURBOLAR	Rueda compresora GT1749S (Hyundai 38.0-6.0) (433256-0003) (Turbola	OFERTA
38-163 K	TURBOLAR	Rueda compresora HE221W (Turbolar) Use 38-300 MFS	OFERTA
38-195 K	TURBOLAR	Rueda compresora K24 Iveco 90E135 (5324 123 2012/2017) (Turbolar)	OFERTA

**Los precios que no se expresan en \$ (PESOS), están sujetos al factor indicado**

Formulario: Novedades.rpt

programa: frmmodulo1

Fecha y hora de impresión: 13/05/2016

**www.diesellider.com.ar**